## **Evaluation of Physical Barriers- Moreno Valley / March Field Station**

Address: 14160 Meridian Pkwy, Riverside, CA 92518



Year of Construction: Station- 03/12/2010

Applicable ADA Standards: DOT's ADA standards (2006), and DOJ 2010 ADA Standards.

Note: Criteria used to assess the elements were based on DOJ 2010 standards, DOT's ADA standards (2006), DIB 82-06, and PROWAG

These elements were assessed to identify any physical barriers:

1. Curb ramps (1a, 1b, 2a, 2b, 3a-3b, 4a-4b, 5a- 5b)

Evaluation Date: 08-05-2021


- 2. Pedestrian road crossings
  - a. Pedestrian push button signals (where applicable)
- 3. Accessible routes
  - a. Walking surfaces
  - b. Elevators
  - c. Pedestrian Bridge
  - d. Stairs
  - e. Ramps
- 4. Platforms
  - a. Walking surfaces
  - b. Mini High platforms and ramps
- 5. Pedestrian rail crossings
- 6. Access to public amenities
  - a. Ticket Vending/validation machines (TVM),
  - b. Drinking fountain
  - c. Communication Systemspassenger information phones, blue emergency phones, yellow call boxes, service phones, emergency phones.
  - d. Trash cans,
  - e. Vending machines
  - f. Benches
- 7. Accessible parking spaces
- 8. Bus stops
- 9. Signage
- 10. Public Address Systems
- 11. Staff facilities
  - a. Security Staff Facility
  - b. Dumpster
  - c. Storage and Maintenance Building
  - d. Staff Toilet

Issues	Recommendations	Comments
1. Curb Ramps		
1a, 1c - OK 1b - Trip hazard due to level change in Detectable Warning Surface (DWS) tile 2a- Trip hazard due to level change in DWS. 2b, 2c - OK 3a - Trip hazards due to level change in DWS. Level change at the concrete base needs maintenance. Cross slope of curved ramp may exceed 2%. 4a, 4b-OK 5a, 5B - Not on an accessible route yet. No issues found.  Need to verify slope of the gutters at all curb ramps adjoining gutters with properly sized instrument  1b 2b 2b 3a	See Item 3 below	Adjoining surface maximum slope  20  Figure 406.2 Counter Slope of Surfaces Adjacent to Curb Ramps  This evaluation does not include curb ramps outside the RCTC boundary. RCTC is not responsible for maintaining the accessible routes outside of RCTC boundary.  When repairs begin, use proper and precise instruments (4-foot smart level and 2-foot smart level) to fit within the curb ramp width and the adjacent gutter to measure ramp slopes, cross slopes, and counter slopes at all curb ramps (all stations). The long slope of ramp shall not exceed 1:12 (8.33%). Slope of flared sides shall not exceed 1:10 (10%), the gutter slope shall not exceed 1:20 (5%). Cross slope of the ramp and landing shall not exceed 1:50 (2%)  Use smart level instruments, calibrated in accordance with manufacturer's instructions before taking measurements.

laguas	Decemmendations	Commonto
Issues	Recommendations	Comments
2. Pedestrian Road crossings		
No issues found with pedestrian crossings on the accessible routes 3a-3b and 4a-4b.		
a) Pedestrian Push Button- Not Applicable	No action by RCTC	
3. Accessible Routes		
a) Walking surface		
Aisles at the ADA parking spots have level changes where asphalt is higher than the concrete	Examine all parking aisles, accessible routes, and curb ramps.  Every joint deeper than ½" and wider than ½" shall be filled.  Every level change along the accessible route greater than ½" and less than ½" height needs to be beveled (1:2) slope or repaired.  Every level change greater than ½" needs to have a ramped surface (1:12) slope.	long dimension perpendicular to dominant direction of travel  13  Figure 302.3  Elongated Openings in Floor or Ground Surfaces  14  13  Figure 303.3  Beveled Change in Level  14  Figure 303.2  Vertical Change in Level


Issues	Recommendations	Comments
b) Elevator		
Not Applicable		
c) Pedestrian Bridge		
Not Applicable		
d) Stairs		
No issues found		
e) Ramps		
No issues found		

Recommendations Comments Issues 4. Platforms a. Walking Surfaces General: Joints and gaps in concrete to be repaired or maintained for Examine all pedestrian compliance with 302.3, 303.2, and 303.3. routes and repair all dominant direction of travel cracks. Every joint in concrete deeper than 1/4" and wider than ½" shall be filled. long dimension perpendicular to dominant direction of travel Every level change along the accessible route greater than 1/4" and less than 1/2" height needs to be beveled (1:2) slope or repaired. ½ max Every level change greater than 1/2" needs to Figure 302.3 have a ramped surface **Elongated Openings in Floor or Ground Surfaces** (1:12) slope.



Issues	Recommendations	Comments
b. Mini High Platforms and Ramps	Recommendations	
No Issues found		
5. Pedestrian Rail Crossings		
DWS does not extend 36 inches in the direction of travel as required by DIB-82-06 4.3.14 Detectable Warning Surface. DWS complies per 2010 ADA standards and <b>PROWAG R305.1.4</b>	Provide 36 inches wide DWS to comply with DIB 82-06	R305.2.5 Pedestrian At-Grade Rail Crossings
		At pedestrian at-grade rail crossings not located within a street or highway, detectable warning surfaces shall be placed on each side of the rail crossing. The edge of the detectable warning surface nearest the rail crossing shall be 1.8 m (6.0 ft) minimum and 4.6 m (15.0 ft) maximum from the centerline of the nearest rail. Where pedestrian gates are provided, detectable warning surfaces shall be placed on the side of the gates opposite the rail.
T		Figure R305.2.5 Pedestrian At-Grade Rail Crossings






**PROWAG R305.1.4** Size, Detectable warning surfaces shall extend 610 mm (2.0 ft) minimum in the direction of pedestrian travel.

**DIB-82—06 4.3.14**: Detectable Warning Surface - Detectable warning surfaces shall extend 3 feet in the direction of pedestrian travel.

Issues	Recommendations	Comments
6. Amenities		
a) TVM's		
TVM's are not in RCTC's scope. However, they are considered as being compliant to ADA requirements per information found on website <a href="https://metrolinktrains.com/ticketsOverview/where-to-buy/ticket-machines/">https://metrolinktrains.com/ticketsOverview/where-to-buy/ticket-machines/</a>	Adequate clear space is provided at TVM's. No action.	
b) Drinking Fountains		
Drinking Fountain is not provided at this station.	No action by RCTC	
c) Telephones/ Communication Systems	See Attachment 9, Action Plan for recommendations	Clear space and reach ranges are found to be compliant. All instruments are to be tested regularly for compliance by the responsible authorities.
i. Passenger Information Phone: OK	No action by RCTC	704.2.1 Clear Floor or Ground Space. A clear floor or ground space complying with 305 shall be provided. The clear floor or ground space shall not be obstructed by bases, enclosures, or seats.  704.2.2 Operable Parts. Operable parts shall comply with 309. Telephones shall have push-button controls where such service is available.  Figure 308.3.2 Obstructed High Side Reach  Obstructed High Forward Reach



Recommendations	Comments
No action by RCTC. Number of ADA and van accessible spaces is compliant.	208.2 Minimum Number. Parking spaces complying with 502 shall be provided in accordance with Table 208.2 except as required by 208.2.1, 208.2.2, and 208.2.3. Where more than one parking facility is provided on a site, the number of accessible spaces provided on the site shall be calculated according to the number of spaces required for each parking facility.  Table 208.2 Parking Spaces
	Total Number of Parking Spaces Minimum Number of Required Provided in Parking Facility Accessible Parking Spaces
	1 to 25
	26 to 50 2
	51 to 75
	76 to 100 4
	101 to 150 5
	151 to 200 6
	201 to 300 7
	301 to 400 8
	401 to 500 9
	501 to 1000 2 percent of total
	1001 and over 20, plus 1 for each 100, or fraction thereof, over 1000
Examine regularly and maintain accessible routes to permit safe ambulation.	810.2.3 Connection. Bus stop boarding and alighting areas shall be connected to streets, sidewalks, or pedestrian paths by an accessible route complying with 402.
No action by RCTC. Signage is by SCRRA/Metrolink	810.6 Rail Station Signs. Rail station signs shall comply with 810.6.  EXCEPTION. Signs shall not be required to comply with 810.6.1 and 810.6.2 where audible signs are remotely transmitted to hand-held receivers, or are user- or proximity-actuated.  SCRRA/Mertolink is responsible for the signage.
	No action by RCTC. Number of ADA and van accessible spaces is compliant.  Examine regularly and maintain accessible routes to permit safe ambulation.  No action by RCTC. Signage is by

Issues	Recommendations	Comments
10. Public Address		
There are LCD/LED Message screens at the stations that will show information that is conveyed on the public address system, both of which are controlled by SCRRA. These are not under RCTC's authority.	No action by RCTC	810.7 Public Address Systems. Where public address systems convey audible information to the public, the same or equivalent information shall be provided in a visual format.
Written Emergency Evacuation procedures were not available	Update any existing emergency evacuation procedures to include evacuation of individuals with disabilities during an emergency.	Special procedures are required for assisting individuals with disabilities from a facility during an emergency.
11. Staff Facilities		
a) Security Staff Facilities		
The guard booth is provided as a shelter against weather and for use during breaks by security staff, who are expected to walk around the station site and physically address emergency situations.	Inform all contractors of their ADA obligations	Station Security services are contracted out and an ADA evaluation of the facilities used by the station security was not conducted as it is not Public Accessible and the Security Contractor requirements require the guards to be able to walk around the station site and physically address emergency situations.
b) <u>Trash / Dumpster Enclosure</u>		
The trash dumpster is on an ADA compliant route and provided with accessible gate	No Action	203.9 Employee Work Areas. Spaces and elements within employee work areas shall only be required to comply with 206.2.8, 207.1, and 215.3 and shall be designed and constructed so that individuals with disabilities can approach, enter, and exit the employee work area.

Issues	Recommendations	Comments
c) Storage and Maintenace Building		
No issues found. Accessible route and doors are provided.		Same as item 11b above.
d) Staff toilet		
<ul> <li>i. Sign is not provided</li> <li>ii. The paper tower dispenser appears to be installed higher than 48 A.F.F.</li> </ul>	Provide compliant signs as per 216.2.  Relocate paper towel dispenser at 48" max. to comply with 308.2.2 and 308.3.1	216.2 Designations. Interior and exterior signs identifying permanent rooms and spaces shall comply with 703.1, 703.2, and 703.5.  20 max  ->20 max